




RS-80 BILY




(A1) x58 8x35 	(C2) x 8 euro 6x13 	(ZN) x4 
(SP) x8 	(W4) x8 3.5 x 20 	(N1) x20 3,5x13 
(M) x1 	(O2) x 4 	(KF) x10 7 x 50 
(P1) x16 	(G4) x80 	(T3) x 2 L=300 
(F1) X18 	(E1) x18 ø15 x 12mm 	x18 


box 1/2



3 - x 1
4 - x 2
5 - x 1
13 - x 2

box 2/2






1 - x 1
2 - x 1
6 - x 4
7 - x 1
8 - x 4
9P - x 1
9L - x 1
10 - x 2
11 - x 4
12 - x 2
14 - x 2
15 - x 2







A



3,5x20

G4



A=B



A B