







RS-60






N2  20,3 x 18	M3  x 18	E4  x 12	S1  3,5x16 x 12	E1  8x30 x 40	D2  x 8
T1  x 4	Z2  x 70	P3  L=300 x 3	S15  6x8 x 12	M2  x 6	GLUE  x 1

1	x 1
2	x 1
3	x 2
4	x 3
5	x 1
6	x 1


7	x 2
8	x 2
9	x 6
10	x 3
11	x 3
12	x 3


1


N2  20,3 x 8	P3  L=300 x 3	S15  6x8 x 12	E1  8x30 x 4	D2  x 8	M3  x 4
--	---	---	---	---	---



M3  x 8	E1  8x30 x 8
---	--





N2  20,3 x 4




2


E1  8x30 x 16




3




4




5

P2  L=300 x 3	S1  3,5x16 x 12	Z2  x 21
---	---	---




x 3

Z2  x 49
T1  x 4



6

 x 1

- 1 
- 2 
- 3 
- 4 

